MyQ Lexmark Embedded Terminal 8.1

MyQ Lexmark Embedded Terminal 8.1 (patch 7)

20 October, 2023

Bug Fixes

- Custom logo was displayed blurred.

MyQ Lexmark Embedded Terminal 8.1 (patch 6)

1 September, 2023

Improvements

- `NEW FEATURE` : It is possible to display My jobs immediately after login. At least one job has to be spooled in Ready jobs.
- `NEW FEATURE` : Lexmark specific parameter is available in Configuration profiles.
- `NEW FEATURE` : Top menu is available.

MyQ Lexmark Embedded Terminal 8.1 (patch 5)

21 July, 2023

Device Certification

- Model lines CX73x Series, CX93x Series and CX94x Series added for terminal support. (`LIMITATION` : new devices are not certified yet on the server, because we are not able to add them without certification data.)

MyQ Lexmark Embedded Terminal 8.1 (patch 4)

1 March, 2023

Improvements

- `NEW FEATURE` ID Card registration terminal action is implemented.
- Displaying of QR code improved.

Bug Fixes

- Favorites in My Jobs weren't working.
- Incorrect error message was displayed if terminal installation failed because of invalid device's administrator credentials.
- Jobs were printed in incorrect order.
- Language of the Login screen wasn't translated.
- Login via QR code wasn't possible.
- Login wasn't possible with allowed unsecure communication on the server.

MyQ Lexmark Embedded Terminal 8.1 (patch 3)

Bug Fixes

- Custom logo wasn't loaded on the login screen.

MyQ Lexmark Embedded Terminal 8.1 (patch 1) LTS

Bug Fixes

- All jobs were printed after login by card even if Print all after login has been disabled.
- Fixed card login failure.

MyQ Lexmark Embedded Terminal 8.1 RC

Improvements

- **NEW FEATURE** Jobs which aren't possible to print because of Job filters (f.e. printing A3 jobs on A4 printer or Color jobs on BW printer) are marked with proper error message.
- Devices with 4.3" display size are supported for Embedded terminal.
  - Models which should be supported: CS622, CS720, CS725, CS727, CS820, CS827, CS921, CS923, CX622, CX625, MS622, MX522
  - New models will be certified in MyQ server 8.1 RTM+.
- Devices without HDD are supported. **LIMITATIONS** :
  - custom logo and QR code aren't displayed after Lexmark web service restart immediately, they are displayed after few seconds.
  - critical accounting (loss of power during job) is not working and jobs will not be accounted correctly.
  - machine log is not stored and cannot be received.
- More options can be set in Job properties in My jobs:
  - color - BW / Color
  - duplex - Simplex / Duplex long edge / Duplex short edge
  - copies
  - toner saving