**MyQ Xerox Embedded Terminal 7.6**

# MyQ Xerox Embedded Terminal 7.6.15

23 June, 2025

### Bug Fixes

- Remote control panel can't be used on some devices.

# MyQ Xerox Embedded Terminal 7.6.14

13 May, 2024

### Bug Fixes

- Easy Scan - text field doesn't open the Xerox native keyboard.

# MyQ Xerox Embedded Terminal 7.6.13

20 March, 2025

### Improvements

- EIP 5.2 support added.

### Bug Fixes

- Improvements in terminal behaviour when device Altalink 82xx series is used.

# MyQ Xerox Embedded Terminal 7.6.12

22 October, 2024

### Bug Fixes

- Automatic Background Suppression (ABS) is not applied for Easy Copy.

# MyQ Xerox Embedded Terminal 7.6.11

15 July, 2024

### Bug Fixes

- Scanned pages have poor quality because of applying Automatic Background Suppression (ABS). Automatic Background Suppression will be now applied only when Density parameter is set to Lowest, Lower or Low.

# MyQ Xerox Embedded Terminal 7.6.10

26 June, 2024

### Bug Fixes

- "File Access" error message is displayed after the logout of the user on Xerox Altalink devices.

# MyQ Xerox Embedded Terminal 7.6.9

17 May, 2024

### Bug Fixes

- Easy Copy has a background tint when using ECO paper.

# MyQ Xerox Embedded Terminal 7.6.8

1 March, 2024

### Improvements

- Improved communication efficiency and process management during user login.

### Bug Fixes

- Use of embedded is not possible on devices with new EIP 5.1, especially on devices upgraded from EIP 3.7.
- Only one external application can be displayed as Terminal action in the Top menu.
- Some users are unable to log in.
- The default quality of Easy Copy is lower than the default quality of Panel Copy.

# MyQ Xerox Embedded Terminal 7.6.7

23 November, 2023

### Improvements

- NEW FEATURE Application Terminal Action is supported.
- New configuration profile option to disable the Job Limits service. Only use if you have compatibility issues with other applications running on the device.
- Xerox Terminal Package now using default MyQ Web server port for communication. MyQ Print server 8.2 patch 40+ or MyQ Print server 10.1 patch 7+ is required.

### Bug Fixes

- Remote configuration completes successfully, but the device isn't configured correctly if the SNMP settings are incorrect.

# MyQ Xerox Embedded Terminal 7.6.6

14 August, 2023

### Improvements

- Xerox EIP 3.7 devices are automatically restarted after Remote setup.

# MyQ Xerox Embedded Terminal 7.6.5

18 July, 2023

### Bug Fixes

- User can not login to device in some cases due to hanging user session on EIP 3.7 devices.
- Login via Mobile application is not working properly.

# MyQ Xerox Embedded Terminal 7.6.4

19 May, 2023

### Improvements

- Stability of the package has been improved.
- Compatibility with 3rd generation web browsers added.

### Bug Fixes

- Text box on Recharge credit screen is displayed incorrectly.

# MyQ Xerox Embedded Terminal 7.6.3

6 April, 2023

### Bug Fixes

- Panel copy has been accounted to *unauthenticated user on some models.

### Limitations

- SNMP on the server and in the device has to be configured manually to the same values for proper installation. It is possible to use SNMPv1, SNMPv2c or SNMPv3.

# MyQ Xerox Embedded Terminal 7.6.2

10 March, 2023

### Improvements

- Logging to terminal log has been improved.
- Stability of Xerox Terminal service has been improved.

### Changes

- Devices with EIP 3.5 and lower platforms are not officially supported in MyQ Xerox Embedded Terminal 7.6. The installation of the application is possible, but some functions may be limited.

### Bug Fixes

- Improved start of Easy copy.
- Improved start of Easy scan.
- Search of codebook values was not updated if the search result was empty.

# MyQ Xerox Embedded Terminal 7.6.1

### Improvements

- Searching is started after pressing the button for search.

### Bug Fixes

- Remote configuration was not set with SNMPv3.

# MyQ Xerox Embedded Terminal 7.6.0

### Bug Fixes

- Long text overflows to other displayed rows in MyQ users.
- Long user's full name wasn't truncated in Top menu.
- Xerox Terminal service wasn't started when server was booting up.

# MyQ Xerox Embedded Terminal 7.6.0 BETA

## Improvements

- Manual installation of the script with server certificate is not required before the installation of the Xerox embedded package on MyQ server. SSL only is still required.
- NEW FEATURE Easy Copy is supported.
- NEW FEATURE Failover printing from MyQ Desktop Client is supported.
  Limitations of this feature on Xerox embedded:
  - Manual settings of configuration in device web UI for each device using Failover printing via MyQ Desktop Client is required.
  - With these manual settings Top menu/My jobs header with credit/quota limits aren't refreshed automatically, user has to log out and log in to refresh the values.
  - All jobs printed via Failover printing from MyQ Desktop Client are accounted to *unauthenticated.
- NEW FEATURE It is possible to use username + password login method or PIN login method at the same time. LIMITATION Xerox cannot show custom login screen or more than one input field at a time. When combination of username and password or PIN is used, the user is going to be asked for username which can be left blank to enter PIN instead of password.
- NEW FEATURE Scan to Fax server is implemented.
- NEW FEATURE Themes are supported.

## Bug Fixes

- Xerox service failed to start after change of the server default port.

## Limitations

- Text field for entering the PIN or username is displayed if user swipe the card and ID card login method is not enabled. User is not logged in by swiping the card if ID card login method is not enabled.