

MyQ HP Embedded Terminal 10.1 (HP FutureSmart platform)

- Minimum requested support date: **01 February 2023**

What's new in 10.1

Click to see a list of new features available in version 10.1

- Easy Print is supported.
- Folder browsing for Easy Scan is supported.
- Folder browsing for printing is supported.
- Job preview is supported.
- Standalone HP scanners are supported.

MyQ HP Embedded Terminal 10.1 (patch 8)

25 July, 2025

Bug Fixes

- ScannerVision Built-in environment variable USERMAIL is not correctly used in the External Workflow action.
- Some printed jobs are accounted to *unauthenticated user.

MyQ HP Embedded Terminal 10.1 (patch 7)

30 April, 2025

Bug Fixes

- Changed parameters for Easy Scan are remembered only for one reiteration
 - Limitation: Feature is not applicable when Folder Browsing is enabled
- The user session does not finish correctly because of a faulty Print Job.
- User session ends immediately after user logs in.

MyQ HP Embedded Terminal 10.1 (patch 6)

6 December, 2024

Bug Fixes

- Changed parameters for Easy Scan located in the folder required Force configuration for applying.
- The user session does not finish correctly because of faulty Print Job.
- Failed printed jobs are still displayed in My Jobs but it is not possible to print them.
- Unsupported types of parameters for Easy operations blocks usage of Easy operations.

MyQ HP Embedded Terminal 10.1 (patch 5)

26 June, 2024

Bug Fixes

- Easy scan to MyQ Users is greyed out and not possible to use after the scan attempt with empty recipient.

- Jobs that were not printed because the printing of the jobs was stopped after logging off cannot be reprinted during the next user session.
- "404 Not Found" error message is displayed when user tries to print some number of the jobs from My Jobs.

MyQ HP Embedded Terminal 10.1 (patch 4)

28 March, 2024

Improvements

- Setup made easier and more secure by not requiring these device settings to be enabled: Allow firmware update, Allow installation of legacy packages, Enable PDL drive access, Enable PS drive access.

Bug Fixes

- Easy scan to OneDrive fails if the folder name contains "&" character.
- Scan is occasionally not delivered.
- Terminal stops working if the user session is longer than 30 minutes. **LIMITATION** MyQ Print Server 10.1 patch 10 and newer is required.

MyQ HP Embedded Terminal 10.1 (patch 3)

15 December, 2023

Improvements

- Easy Scan: If you change the scan parameters, you can reuse them for another scan. The parameters are reset only when you return to the Top Menu.

Bug Fixes

- Easy print: Job options are not translated, the options are displayed in English language only.
- When the terminal is installed, the Supplies screen is not accessible on the device panel.
- Easy Print: User is not automatically redirected to the Top menu if cloud storage is not connected.

MyQ HP Embedded Terminal 10.1 (patch 2)

21 July, 2023

Bug Fixes

- Incorrect error message is displayed if user doesn't have rights for using any projects and tries to use Easy Print.

MyQ HP Embedded Terminal 10.1 (patch 1)

6 June, 2023

Improvements

- Improvement of contacting Quota server.
- Romanian language is supported. Print server 10.2 Beta 2 or newer is required.
- Warning is displayed in the server log if the server certificate could not be imported to the device automatically during remote configuration and the certificate has to be uploaded manually.

Bug Fixes

- HP native pop-up window with the message "Ready" was displayed during the whole Easy copy operation until all papers were printed on devices with HP FutureSmart 5.5+ firmware.

MyQ HP Embedded Terminal 10.1 RTM

Improvements

- It is possible to disable the Connection to the Quota server to improve the speed of Panel and Easy operations. **LIMITATION**: Accounting accuracy is affected.

Bug Fixes

- Default option is listed instead of the actual value for some Easy Copy and Easy Scan operations.
- Job Preview function buttons are incorrectly displayed on some devices with big display.
- Print from Cloud HP native function isn't removed after terminal uninstallation.
- Text fields on login screen aren't rounded when using white themes.

MyQ HP Embedded Terminal 10.1 RC

Improvements

- Displaying of the QR code on the login screen improved.
- **NEW FEATURE** Standalone HP scanners are supported.

Bug Fixes

- Bad request was displayed if user try to mark job as favorite if he didn't have rights for using the Project.
- Easy Print was not displayed in Exploded mode. Now it is displayed in Print from Cloud.
- Job Properties in Job Preview on small screen's weren't displayed.
- Options in Job Preview on the device panel was displayed incorrectly.

Limitations

- For login via card in Exploded mode with using Credit, Quota or Cost centers the MyQ Login screen has to be active. It is not possible to login from the Sign-in screen or if the device is sleeping.

MyQ HP Embedded Terminal 10.1 BETA1

Improvements

- Improved behavior of projects when there are no projects with rights available for the user.
- Improved the projects assigning when user has no rights for the project anymore.
- UI improved.
- **NEW FEATURE** Easy Print is supported.
- **NEW FEATURE** Folder browsing for Easy Scan is supported.
- **NEW FEATURE** Folder browsing for printing is supported.
- **NEW FEATURE** Job preview is supported.

Bug Fixes

- Custom logo is not displayed correctly on devices with small screen display.
- QR code is visible in the 2nd screen of 2-factor login and in Admin Login.